

AM Machinery inspection certificate

New Holland 470FI

#21170



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 470FI** built in **2008**, with our internal stock number **21170**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information: <https://www.ammachinery.nl/new-holland-470fi.html>

Technical specifications

| | | | |
|------------|-------|---------------------|------|
| Partnumber | 21170 | Year of manufacture | 2008 |
|------------|-------|---------------------|------|

Options

2) Short Description

For sale 2008 New Holland FI470 (Kemper 375) 10 row corn header to fit New Holland FR series Forage harvesters

3) Product Images





4) Inspection Report

Condition
Header

| | | | |
|-------------------------------|---------|-------------------------------|-------------|
| Stocknumber | 21170 | Brand | New Holland |
| Model | FI470 | Amount of rows | 10 |
| Working width | 7500 mm | Autosteer sensor | N.A. |
| Header lateral tilt | N.A. | Header height control sensors | N.A. |
| Header speed gearbox shifting | V | Cutting knives | ★ ★ ☆ ☆ ☆ ☆ |
| Drum bearings | V | Cleaners | V |
| Drums | V | Drum cleaners / scrapers | X* |
| Knife discs | V | Drive shaft | V |
| Drive line couplers | X* | Drive chains and belts | X* |
| Crop dividers | X* | Oil levels | V |
| Down corn augers | V | Ground skid plates | X* |
| Fold cylinders | V | Hydraulic hoses/lines | V |
| Transport accident prevention | N.A. | Support wheel(s) | N.A. |
| Support legs | X* | Feeder auger | N.A. |
| Feeder auger bearings | N.A. | Wearplates | V |

5) Recommended Repairs

Belt replacement crop divider kemper 300 LH side
 Kemper 300 coupler RH outer side replacement
 Kemper 300 plus skid plate 1e left replacement
 Kemper 300 plus skid plate 2e left replacement
 Kemper 300 plus skid plate 5e left replacement
 Kemper 300 plus skid plate 10e left replacement
 Kemper 375 knife and cleaner replacement
 Lock repair legs LH New style weld on
 Welding 2 hours
 Welding 4 hours