

AM Machinery inspection certificate

Kemper 360

#23140



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 360** built in **2011**, with our internal stock number **23140**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-360-23140.html>

Technical specifications

Partnumber	23140	Year of manufacture	2011
------------	-------	---------------------	------

Options

2) Short Description

For Sale, 2011, Kemper 360 8 row corn header. With header lateral tilt. This header has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23140	Brand	Kemper
Model	360	Amount of rows	8
Working width	6 meter	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Cutting knives	★★★★☆☆	Drum bearings	X*
Cleaners	V	Drums	V
Drum cleaners / scrapers	V	Knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	X*	Crop dividers	X*
Oil levels	V	Down corn augers	X*
Ground skid plates	X*	Fold cilinders	V
Hydraulic hoses/lines	X*	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	X*
Feeder auger	N.A.	Feeder auger bearings	N.A.
Wearplates	X*		

5) Recommended Repairs

Belt replacement crop divider kemper 300 LH side
 Kemper 300 hose's to coupler Claas 492/493
 Kemper 300 Lh bolt replacement
 Kemper 300 plus RH mainframe outer feedroller drum bearing replacement.
 Kemper 300 plus skid plate 1e left replacement
 Kemper 300 plus skid plate 3e left replacement
 Kemper 300 plus skid plate 8e left replacement
 Kemper 300 to Claas angled wearplate feedrolls replacement
 Kemper 300/445/4500 down corn auger pully replacement RH
 Kemper 300445/4500 down corn auger pully replacement LH
 Kemper 360 LH fold cilinder Hoses replacement
 Kemper 360 RH fold cilinder Hoses replacement
 Welding 2 hours