

AM Machinery inspection certificate

New Holland 750SFI

#23171



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 750SFI** built in **2012**, with our internal stock number **23171**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information: <https://www.ammachinery.nl/new-holland-750sfi-23171.html>

Technical specifications

Partnumber	23171	Year of manufacture	2012
------------	-------	---------------------	------

Options

2) Short Description

For sale 2012 New Holland 750SFI 10 row corn header. This header has been inspected.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23171	Brand	New holland
Model	750SFI	Amount of rows	10
Working width	7.5 m	Autosteer sensor	X*
Header lateral tilt	N.A.	Header height control sensors	N.A.
Cutting knives	★☆☆☆☆	Drum bearings	V
Cleaners	X*	Drums	X*
Drum cleaners / scrapers	V	Drive shaft	V
Drive line couplers	V	Drive chains and belts	N.A.
Crop dividers	V	Oil levels	V
Down corn augers	N.A.	Ground skid plates	V
Fold cilinders	V	Hydraulic hoses/lines	V
Transport accident prevention	N.A.	Support wheel(s)	V
Support legs	X*	Wearplates	V

5) Recommended Repairs

Autosteer sensor rubber replacement
 Kemper 300Plus disc replacement RH 1e disc
 Kemper 300Plus disc replacement RH 2e disc
 Kemper 300Plus disc replacement RH 5e disc
 Kemper 300Plus disc replacement RH 6e disc
 Kemper 300Plus disc replacement RH 7e disc
 Kemper 300Plus disc replacement RH 10e disc
 Kemper 375 knife and cleaner replacement
 Lock repair legs LH New style weld on
 New Holland 750sfi 4e Feeder drum LH replacement
 New Holland 750sfi 4e Transport drm replacement after sn:122139
 New Holland 750sfi 5e Feeder drum LH replacement
 New Holland LH front supportleg bracket replacement
 New Holland LH front supportleg replacement