

AM Machinery inspection certificate

# New Holland 420FI

#23126



Price on request



**AMMACHINERY**

**AMMACHINERY**

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 420FI** built in **2013**, with our internal stock number **23126**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information: <https://www.ammachinery.nl/new-holland-420fi-23126.html>

### Technical specifications

Partnumber	23126	Year of manufacture	2013
------------	-------	---------------------	------

### Options

## 2) Short Description

---

For Sale, 2013, New Holland 420FI 6 row corn header. This header has been inspected. The inspection report can be downloaded from our website.

## 3) Product Images

---







## 4) Inspection Report

---

Condition  
Header

Stocknumber	23126	Brand	New Holland
Model	420FI	Amount of rows	6
Working width	4.5 M	Autosteer sensor	N.A.
Header lateral tilt	N.A.	Header height control sensors	N.A.
Cutting knives	★★★★☆	Drum bearings	V
Cleaners	V	Drums	V
Drum cleaners / scrapers	X*	Knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	V	Crop dividers	X*
Oil levels	V	Down corn augers	V
Ground skid plates	V	Fold cylinders	V
Hydraulic hoses/lines	X*	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Feeder auger	N.A.	Feeder auger bearings	N.A.
Wearplates	V		

## 5) Recommended Repairs

---

750 sfi hoses to coupler FR replacement

Welding 2 hours

Welding 3 hours