

AM Machinery inspection certificate

Claas ORBIS 750

#23156



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas ORBIS 750** built in **2013**, with our internal stock number **23156**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-orbis-750-23156.html>

Technical specifications

Partnumber	23156	Year of manufacture	2013
------------	-------	---------------------	------

Options

2) Short Description

For sale 2013 Claas Orbis 750 10 row corn header. This header has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23156	Brand	Claas
Model	Orbis 750	Amount of rows	10
Working width	8 M	Autosteer sensor	N.A.
Header lateral tilt	X*	Header height control sensors	V
Cutting knives	★ ★ ★ ☆ ☆	Drum bearings	X*
Cleaners	X*	Drums	V
Drum cleaners / scrapers	X*	Knife discs	V
Drive shaft	V	Drive line couplers	V
Crop dividers	X*	Oil levels	V
Down corn augers	X*	Ground skid plates	V
Fold cilinders	V	Hydraulic hoses/lines	V
Transport accident prevention	N.A.	Support wheel(s)	N.A.
Support legs	X*	Wearplates	V