AM Machinery inspection certificate

# Kemper Gearbox Kemper 460-475-490 Plus

#920032

**€0,00**

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 – 2066603
sales@ammachinery.nl
https://www.ammachinery.nl/

Dear sir/madame,

Thank you for your interest in our **Kemper Gearbox Kemper 460-475-490 Plus** built in ,with our internal stock number **920032**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information: **https://www.ammachinery.nl/catalog/product/view/id/3461/s/kemper-gearbox-kemper-460-475-920032/**

**Technical specifications**

| | |
|---|---|
| Partnumber | 920032 |

**Options**

## 2) Short Description

NEW-LCA106907/LCA106903S Main Drum, left rotating for Gearbox Kemper 460-475-490 Plus

## 3) Product Images

https://www.ammachinery.nl/catalog/product/view/id/3461/s/kemper-gearbox-kemper-460-475-920032/

Download date: 4/25/24

## 4) A&M PREMIUM Warranty

All our equipment is inspected with the Harvester-Guard (R) inspection software. This certificate declares that this forage harvester has A&M PREMIUM warranty on:

1. All inspected CROP-FLOW components with a 3, 4 or 5 star rating.
2. All CROP-FLOW bearings which have status approved.

**Warranty on repairs:**

Components with 1 or 2 star rating are subject for repair and have no warranty. In case A&M Machinery is ordered to repair the 1 and 2 stars components then warranty is in place, as repair implies upgrade to 5 stars or status approved.

Eventually repairs are reported in the "A&M PREMIUM or A&M EXCLUSIVE warranty certificate & terms" document.


https://www.ammachinery.nl/catalog/product/view/id/3461/s/kemper-gearbox-kemper-460-475-920032/
Download date: 4/25/24