AM Machinery inspection certificate

Claas Jaguar 960

#22057

Price on request

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 – 2066603
sales@ammachinery.nl
https://www.ammachinery.nl/

Dear sir/madame,

Thank you for your interest in our **Claas Jaguar 960** built in **2011** ,with our internal stock number **22057**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:
https://www.ammachinery.nl/claas-jaguar-960-22057.html

Technical specifications

Partnumber	22057	Brand	Claas
Model	Jaguar 960	Year of manufacture	2011
Series	494	Engine hours	4831
Road speed (km/h)	40	Drum hours	3555
Attr 2 or 4 wheel drive	4 WD	Amount knives installed	36
Configuration	Corn	Engine brand	Mercedes-Benz
Engine Brand	Mercedes-Benz	Engine type	V8
Engine type	V8	Front Tires Brand	Trelleborg
Rear Tires Brand	Trelleborg	Front Tires Size	900/60R32
Rear Tires Size	600/65R28	Front Tires profile	85
Rear Tires Profile	88	Emission Level	Tier 3
Drum type	V-max		

Options

Auto lubrication	Yes	Rockstopper	Yes
Spout camera	Yes	Rear weights	Yes
Trailer hitch	Yes	Yield & moisture mapping	Yes
NIR sensor	Yes	Tire pressure system	Yes
Innoculant factory installed	Yes	Climate control	Yes
Electrical adjustable mirrors	Yes	Refrigurator	Yes
Electrical KP-gap adjustment	Yes	Air compressor	Yes
Xenon lights	Yes	LED lights	Yes
Sunblinds window(s)	Yes		

2) Short Description

for sale 2011 Claas Jaguar 960 forage harvester 4WD full option including Claas Orbis 750 10 row corn header, 4833 engine hours and 3555 cutting hours, 36 knife drum, kernel processor (corn cracker), autolube, stone detector, spout camera, rear weights, trailer hitch, Yield sensor, tire pressure regulation system, innoculant system factory installed and refrigurator

3) Product Images

https://www.ammachinery.nl/claas-jaguar-960-22057.html

Download date: 4/25/24

4) Inspection Report

Levels

Anti-freeze level in °C	-30	Cooling liquid level	V
Engine oil level	X	Hydraulic oil level	V

Condition
Knive drum

Condition knives	10%	Shearbar front surface	★★★★☆
Shearbar rear surface	★☆☆☆☆	Shearbar active position	Rear
Lefthand Knive drum bearing	x*	Righthand Knive drum bearing	V
Knife drum bottom plate	★★★☆☆	Knife drum rear plate	★★★☆☆
Sharpening stone	★★★★☆		

Kernal processor

Gras chute liner		★☆☆☆☆	

Feedrolls

Upper front feedroll	★★★☆☆	Upper rear feedroll	★★★☆☆
Smooth roll	★★★☆☆	Smooth roll scraper	★★★★☆
Feeder housing wear plates	★★★☆☆		

https://www.ammachinery.nl/claas-jaguar-960-22057.html
Download date: 4/25/24

Corn cave

Corn cave liner	★★★☆☆	Corn cave side liners	★☆☆☆☆

Blower

Blower paddles	80%	Blower liner	★★★☆☆
Blower side liners	★☆☆☆☆	Left hand blower bearing	V
Right hand blower bearing	V		

Transition housing

Transition housing	★★★☆☆	Transition liners	★☆☆☆☆

Spout

Spout turnable wear shims	★★★☆☆	Spout swivel tube	★★★☆☆
Spout complete housing	★★★☆☆	Spout front liner	★☆☆☆☆
Spout rear liner	★★★☆☆	Spout side liners	★★☆☆☆
Inner Spout deflector	★★★☆☆	Outer Spout deflector	★★★☆☆
Spout deflector liners	★★★☆☆		

Engine

Dry engine	V	Waterpump bearings	N.A.
Engine belting	N.A.	Engine belt tensitioners	V
Exhaust system	N.A.	Engine mounting	N.A.
Airfilters	N.A		

Operational Test

Main drive

Main clutch	★☆☆☆☆	Main drive belt	★★★☆☆
Main belt tensioner bearings	V		

Operators station

Rear window wiper	V	Side window wipers	V

https://www.ammachinery.nl/claas-jaguar-960-22057.html

Download date: 4/25/24

5) Operational test

Main drive

Main clutch	★☆☆☆☆	Main drive belt	★★★☆☆
Main belt tensioner bearings	V		

Operational test

Hydrostatic drive neutral	V	Transmission shifting	V
4WD working (if applicable)	V	Foot brakes L/R	V
Parking brake	V	Main clutch working	V
Length of Cutt adjustment	V	Header speed adjustment	V
Header height control	V	Front hydraulics	V
Spout turning	V	Metal detector	V
Spout deflector	V	Sharping system	V
Shearbar adjustment	V	Airconditioning cold	V
Electrical functions cabin	V	Camera(s)	X
Radio	V	Road & Working Lights	V
Free of error codes	V		

6) Recommended repairs

Replace RH small knife disc || oli leakage outer gearbox || new bearings & seals gearbox upper feedrolls || replace knives || replace RH knive drum bearing || replace drum stone cover || replace grass chute liner || replace KP drive tensioner bearings || replace corn cave side liners || replace blower side liners || replace transition liners || turn around shearbar || replace 1st topliner spout || replace LH bearing upper rear feedroller || replace RH bearing metal detector

https://www.ammachinery.nl/claas-jaguar-960-22057.html
Download date: 4/25/24

7) A&M PREMIUM Warranty

All our equipment is inspected with the Harvester-Guard (R) inspection software. This certificate declares that this forage harvester has A&M PREMIUM warranty on:

1. All inspected CROP-FLOW components with a 3, 4 or 5 star rating.
2. All CROP-FLOW bearings which have status approved.

Warranty on repairs:

Components with 1 or 2 star rating are subject for repair and have no warranty. In case A&M Machinery is ordered to repair the 1 and 2 stars components then warranty is in place, as repair implies upgrade to 5 stars or status approved.

Eventually repairs are reported in the "A&M PREMIUM or A&M EXCLUSIVE warranty certificate & terms" document.

https://www.ammachinery.nl/claas-jaguar-960-22057.html
Download date: 4/25/24