

AM Machinery inspection certificate

Claas ORBIS 900

#22158



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas ORBIS 900** built in **2019** ,with our internal stock number **22158**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-orbis-900.html>

Technical specifications

Partnumber	22158	Brand	Claas
Model	Orbis 900	Year of manufacture	2019
Series	900		

Options

2) Short Description

2019 Claas Orbis 900 T3 12 row corn header including autosteer, AHC (automatic header control) and support wheels.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	22158	Brand	Claas orbis
Model	900	Amount of rows	12
Working width	9	Header lateral tilt	V
Header height control sensors	V	Header speed gearbox shifting	V
Cutting knives	★ ★ ★ ☆ ☆	Drum bearings	V
Cleaners	V	Knife discs	V
Drive shaft	N.A.	Drive line couplers	V
Drive chains and belts	N.A.	Crop dividers	X*
Oil levels	V	Down corn augers	X*
Ground skid plates	V	Fold cylinders	V
Hydraulic hoses/lines	V	Transport accident prevention	V
Support wheel(s)	V	Support legs	N.A.
Feeder auger	N.A.	Feeder auger bearings	N.A.

5) Recommended Repairs

Claas Orbis down corn auger coupler replacement RH side
Orbis 450 LH wing inner crop divider replacement
Orbis 450 LH wing inner crop divider support replacement