

AM Machinery inspection certificate

Claas ORBIS 750

#22170



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas ORBIS 750** built in **2017**, with our internal stock number **22170**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-orbis-750-22170.html>

Technical specifications

Partnumber	22170	Year of manufacture	2017
------------	-------	---------------------	------

Options

2) Short Description

For sale 2017 Claas Orbis 750 AC 10 row corn header, nice good working corn header which is been inspected and tested.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	22170	Brand	Claas
Model	Orbis 750	Amount of rows	10
Working width	7450 mm	Header lateral tilt	V
Header height control sensors	V	Header speed gearbox shifting	V
Cutting knives	★★★★☆☆	Drum bearings	X*
Cleaners	X*	Knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	N.A.	Crop dividers	V
Oil levels	V	Down corn augers	X*
Ground skid plates	V	Fold cylinders	V
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	N.A.
Feeder auger	N.A.	Feeder auger bearings	N.A.

5) Recommended Repairs

Cleaner replacement knife disc's Orbis 750 (I52,659)
Down corn auger drive shaft supportbearing repair LH
Orbis 450/750 small drum bearing replacement LH