

AM Machinery inspection certificate

# Kemper 375

#22126



Price on request



**AMMACHINERY**

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 375** built in **2011**, with our internal stock number **22126**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-375-22126.html>

### Technical specifications

Partnumber	22126	Brand	Kemper
Model	375	Year of manufacture	2011

### Options

## 2) Short Description

---

2011 Kemper 375 10 row corn header to fit John Deere 7000 series forage harvesters, including 2 speed gearbox, nice good working corn header which is been inspected and tested.

## 3) Product Images

---





## 4) Inspection Report

---

Condition  
Header

Stocknumber	22126	Brand	Kemper
Model	375	Amount of rows	10
Working width	7.5 meter	Header lateral tilt	V
Header height control sensors	N.A.	Header speed gearbox shifting	V
Cutting knives	★ ★ ☆ ☆ ☆	Drum bearings	V
Cleaners	V	Knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	X*	Crop dividers	V
Oil levels	X*	Down corn augers	V
Ground skid plates	V	Fold cylinders	V
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	X*
Feeder auger	N.A.	Feeder auger bearings	N.A.

## 5) Recommended Repairs

---

Belt replacement crop divider kemper 300 LH side  
 Kemper 300/400 9e gearbox knifedisc breather replacement  
 Kemper 375 knife and cleaner replacement  
 Lock repair legs RH New style weld on