

AM Machinery inspection certificate

Kemper 375

#21223



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 375** built in **2010** ,with our internal stock number **21223**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/kemper-375-21223.html>

Technical specifications

Partnumber	21223	Year of manufacture	2010
------------	-------	---------------------	------


Options

2) Short Description

For sale 2010 Kemper 375 10 row corn header to fit Claas 493, 494, 496, 497 and 498 series forage harvesters, including mechanical contour, 2 speed gearbox, autosteer sensors and several gearboxes replaced. nice good working corn header which is been inspected and tested. Call us today or visit our website for more pictures, video and inspection report.

3) Product Images





4) Inspection Report

Condition
Header

Working width	7.5m	Header lateral tilt	V
Stocknumber	21223	Brand	Kemper
Model	375	Amount of rows	10
Working width	7.5 meter	Header lateral tilt	V
Header height control sensors	N.A.	Header speed gearbox shifting	V
Cutting knives	★ ★ ★ ☆ ☆	Drum bearings	V
Cleaners	V	Knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	V	Crop dividers	V
Oil levels	X*	Down corn augers	V
Ground skid plates	V	Fold cilinders	V
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Feeder auger	N.A.	Feeder auger bearings	N.A.

5) Recommended Repairs

Kemper 300 1e feeder roller gearbox (wing) topseal replacement
Kemper 300 4e feeder roller gearbox (wing) topseal replacement