

AM Machinery inspection certificate

# Claas PU300HD

#23059



Price on request



**AMMACHINERY**

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas PU300HD** built in **2009**, with our internal stock number **23059**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/claas-pu300hd-23059.html>

### Technical specifications

Partnumber	23059	Year of manufacture	2009
------------	-------	---------------------	------

### Options

## 2) Short Description

---

2009 Claas PU300HD Grass Pickup. This pre-owned machine has undergone a thorough inspection, and a downloadable inspection certificate is available on our website. Key Features: 3-Meter Working Width: Compatible with Claas 491/492 Machines

## 3) Product Images

---







## 4) Inspection Report

### Condition Header

Stocknumber	23059	Brand	Claas
Model	Pu 300 HD	Hydraulic hoses / lines	X*
Compression rollers	V	Pick-up teeth	X*
Pick-up cam bearings	V	Compression rollers bearings	V
Feeder auger	V	Feeder auger bearings	X*
Feeder auger fingers	V	Drive chains and sprockets	V
Working width	3 meter	Oil levels	V

## 5) Recommended Repairs

---

Claas 300 driveshaft grease nipple replacement

Claas 300 liftcilinder auger LH seals replacement 428 from 428 0 7746

Claas pick-up teeth replacement 10pc

Claas pu 300 Hoses to lift cilinders compression rollers replacement

Claas PU300 top safety frame net replacement

Claas pu300HD adjustable Support leg RH replacement

Claas pu300HD Feeding auger bearings replacement RH