

AM Machinery inspection certificate

Claas Jaguar 870

#24031



Price on request



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Claas Jaguar 870** built in ,with our internal stock number **24031**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/catalog/product/view/id/44234/s/claas-jaguar-870-24031/>

Technical specifications

Partnumber	24031	Brand	Claas
Model	Jaguar 870	Series	492
Engine hours	6011	Road speed (km/h)	25
Drum hours	4014	Attr 2 or 4 wheel drive	4 WD
Engine Brand	Mercedes-Benz	Engine type	L6
Engine Power HP	438	Engine Power (KW)	322
Front Tires Brand	Good Year	Rear Tires Brand	Michelin
Front Tires Size	800/65R32	Rear Tires Size	500/70R24
Front Tires profile	45	Rear Tires Profile	10
Emission Level	Tier 3		
Type knife drum	Standard		
Knife drum	24		
Amount of knives installed	24		
Kernel processor type	Saw tooth		

Options

Spout extension	Yes	Spout camera	Yes
Rear weights	Yes	Innoculant factory installed	Yes
Climate control	Yes	Refrigurator	Yes
Side window wipers	Yes	Air compressor	Yes
Sunblinds window(s)	Yes		

2) Short Description

2004 Claas Jaguar 870 4WD forage harvester with 6005 engine hours and 4015 cutting hours. Including Kemper 360 8 row corn header. This forage harvester will undergo a 300 point inspection, after which it will be sold with a warranty. This way you always know exactly what the state of your latest investment will be.

3) Product Images



PREMIUM PACKAGE

**SOLD WITH WARRANTY**

30 engine hours / 150 days on
CROP-FLOW components

**AM INSPECTION CERTIFICATE**

300 point inspection
Specs & options check
Functional test

**AM AFTER SALES**

Financing
All-risk shipment insurance



AMMACHINERY





4) Inspection Report

Levels

Anti-freeze level in °C	- 35 °C	Cooling liquid level	V
Engine oil level	X*	Hydraulic oil level	V
Left hand front end drive oil level	X*	Rear axle oil level	V
Left hand rear end drive oil level	V	Right hand rear end drive oil level	V
Upper feedrolls gearbox oil level	X*	Lower feedrolls gearbox level	X*
Gearbox oil level	V	4WD gearbox oil level	X*
Fan drive gearbox oil level	X*	Main gearbox pump drive	V
Brake fluid	V		

Condition

Knife drum

Type knife drum	Standard	Knife drum	24
Amount of knives installed	24	Knife condition	42%
Knife drum configuration	Corn	Shearbar front surface	★ ★ ☆ ☆ ☆
Shearbar rear surface	★ ★ ★ ☆ ☆	Shearbar active position	Rear
Left hand Knife drum bearing	V	Right hand Knife drum bearing	V
Knife drum bottom plate	★ ★ ★ ☆ ☆	Knife drum rear plate	★ ★ ★ ☆ ☆
Knife drum front cover	★ ☆ ☆ ☆ ☆	Knife drum stone cover	★ ★ ☆ ☆ ☆
Sharpening stone	★ ★ ☆ ☆ ☆	Left hand lift cilinder	V
Right hand lift cilinder	V		

Kernel processor

Gras chute liner	★ ★ ☆ ☆ ☆	Kernel processor rolls	★ ★ ★ ☆ ☆
Kernel processor type	Saw tooth	Kernel processor front roller left hand bearing	V
Kernel processor front roller right hand bearing	V	Kernel processor rear roller left hand bearing	V
Kernel processor rear roller right hand bearing	V	Kernel processor drive belt	★ ★ ★ ☆ ☆
Kernel processor drive tensioner bearings	V	Kernel processor drive idler roller	X*
Kernel processor housing	★ ★ ☆ ☆ ☆	Tensioner springs gap adjustment	X*

Feedrolls

Upper front feedroll ★★☆☆☆

Upper rear feedroll ★★☆☆☆

Metal detector roll wear strips ★☆☆☆☆

Smooth roller chain coupler V

Upper front feedroller left hand bearing V

Upper rear feedroller right hand bearing V

Metal detector roll right hand bearing V

Smooth roll right hand bearing V

Belt main drive feedrolls V

Upper feedroller arm bushing V

Housing opening rubbers X*

Upper feedrolls tension springs V

Upper feedrolls arm bump stops V

LOC Gearbox X*

Upper front feedroll wear strips ★★☆☆☆

Metal detector roll ★★☆☆☆

Smooth roll ★★☆☆☆

Smooth roll scraper ★★☆☆☆

Upper rear feedroller left hand bearing V

Metal detector roll left hand bearing V

Smooth roll left hand bearing V

Main drive feedrolls V

Tensioner belt main drive feedrolls V

Feeder housing wear plates ★★☆☆☆

Upper feedrolls drive shaft V

Upper feedrolls shock absorber X*

Lower feedrolls gearbox X*

Gearbox upper feedrolls X*

Corn cave

Corn cave liner ★★☆☆☆

Corn cave top liner ★★☆☆☆

Corn cave side liners ★★☆☆☆

Blower

Blower paddles	90%	Blower liner	★★★★☆☆
Blower housing	V	Left hand blower bearing	V
Right hand blower bearing	V	Blower angled liner	X*

Transition housing

Transition housing	★★★★☆☆	Transition liners	★★★★☆☆
--------------------	--------	-------------------	--------

Spout

Spout turnable wear shims	★★★★☆☆	Spout swivel tube	★★★★☆☆
Spout complete housing	★★★★☆☆	Spout front liner	★★★★☆☆
Spout rear liner	★★★★☆☆	Spout side liners	★★★☆☆☆
Spout extention	★★★★☆☆	Spout extention liner	★★★★☆☆
Inner Spout deflector	★★★★☆☆	Outer Spout deflector	★★★★★★
Spout deflector liners	★★★★☆☆		

Engine

Dry engine	X*	Waterpump bearings	V
Engine belting	V	Engine belt tensioners	V
Exhaust system	X*	Engine mounting	V
Airfilters	X*	Rotary air screen	V
Cleaner cooling package	N.A.	Engine belting idler roller	V
Fan drive gearbox	V		

Operational Test

Main drive

Main clutch	★★★★☆☆	Main drive belt	★★★★☆☆
Main belt tensioner bearings	V		

Drive train

Front drive shaft's and coupler's	V	Tires condition	V
Rear axle drive shaft	V	Rear axle stub axle	X*
Rear axle ball joint	V	Steering cylinders	V
Operators station			
Front window	V	Rear window	V
Cab door	V	Cab door latch	V
Cab right hand window	V	Cab roof	V
Cab front bottom cover	V	Mirrors	V
Joystick	V	Armrest control panel	V
Steering wheel adjustment	V	Front window wiper	X*
Side window wipers blade	X*	Cab air filter	X*
Seat	V		
Machine body			
Front cover	V	Left hand cover	V
Right hand cover	V	Rear cover	V
Electrical			
Head lights	V	Rear lights	V
Brake lights	V	Turn signal/hazard lights	V
Rotary beacon	V	Dome lights	X*
Cab upper front work lights	V	Cab side work lights	V
Fender work lights	V	Upper rear work lights	N.A.
Lower rear work lights	N.A.	Spout work lights	V
Fuel gauge	V		

Functional test

Engine oil pressure low idle cold	6	Engine oil pressure high idle cold	6.8
Engine oil pressure low idle operating temperature	3.3	Engine oil pressure high idle operating temperature	5.5
Hydrostatic drive neutral	V	Transmission shifting	V
4WD working (if applicable)	V	Foot brakes L/R	V
Parking brake	X*	Main clutch working	V
Autolube	N.A.	Length of Cutt adjustment	V
Header speed adjustment	V	Header height control	V
Header Lateral Tilt (if applicable)	N.A.	Front hydraulics	V
Dump valve (high flow hydraulics)	N.A.	Spout turning	V
Metal detector	V	Spout deflector	V
Sharping system	V	Shearbar adjustment	V
Kernel processor gap adjustment	V	Airconditioning cold	V
Electrical functions cabin	V	Camera(s)	V
Radio	V	Road & Working Lights	V
Free of error codes	V		

Header

Stocknumber	23163	Brand	Kemper
Model	Champion 360	Amount of rows	8
Working width	6 M	Autosteer sensor	N.A.
Header lateral tilt	N.A.	Header height control sensors	N.A.
Cutting knives	★★★★☆☆	Drum bearings	X*
Cleaners	X*	Drums	V
Drum cleaners / scrapers	X*	Knife discs	X*
Drive shaft	X*	Drive line couplers	V
Drive chains and belts	X*	Crop dividers	X*
Oil levels	X*	Down corn augers	X*
Ground skid plates	X*	Fold cilinders	X*
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Wearplates	X*		

5) Operational test

Main drive

Main clutch	★★★★☆☆	Main drive belt	★★★★☆☆
Main belt tensioner bearings	V		

6) Recommended Repairs

4WD gearbox seal replacement output shaft
 Airfilters replacement OM457LA (00 0077 382 1+ 00 0077 367 2)
 Belt replacement crop divider kemper 300 RH side
 Blower angled liner replacement
 Cab air filters replacement

Cleaners replacement Kemper 360 (plus)
Cleaners support replacement Kemper 360
Drum and knife disc bearing replacement Kemper 300 4e left
Drum and knife disc bearing replacement Kemper 300 5e left
Drum and knife disc bearing replacement Kemper 300 7e left
Exhaust manifold gaskets replacement OM457LA
Fan drive gearbox oil replacement
Feeder housing lower rear RH wear plate
Front window wiperblade replacement
Gearbox upper feedrolls housing replacement 492
Grass chute liner replacement
Kemper 300 cover middle main clutch replacement
Kemper 300 disc replacement LH 3e disc
Kemper 300 disc replacement LH 4e disc
Kemper 300 disc replacement LH 5e disc
Kemper 300 disc replacement LH 6e disc
Kemper 300 down corn auger top bearing replacement LH
Kemper 300 down corn auger top bearing replacement RH
Kemper 300 middle cropdivider replacement
Kemper 300 skid plate 1e left replacement
Kemper 300 skid plate 2e left replacement
Kemper 300 skid plate 3e left replacement
Kemper 300 skid plate 4e left replacement
Kemper 300 skid plate 5e left replacement
Kemper 300 skid plate 6e left replacement
Kemper 300 skid plate 7e left replacement
Kemper 300 skid plate 8e left replacement
Kemper 300/400 down corn auger tensioner bearing replacement RH
Kemper 300/445/4500 down corn auger pully replacement LH
Kemper 360 LH wing seals gearboxes replacement frame
Kemper 360 RH wing seals gearboxes replacement frame
Kemper 360 seal replacement fold cylinder LH side
Kernel processor drive idler roller bearing replacement 492
Kernel Processor lower liners replacement
Knife drum front cover replacement
Left hand front end drive inner seal replacement
Lh seal housing replacement
Loc Gearbox hydraulic hoses feedroll reverser replacement
LOC gearbox seal main driveshaft replacement
Loc Gearbox shaft headerdrive replacement
Lower gearbox complete overhaul
Mercedes OM457LA oil change
Metal detector roll wearstrips replacement
Parking brake adjustment
Rh seal housing replacement
RH stone cover replacement 492
Right hand front end drive inner seal replacement
Sharpening stone chain adjustment
Side window wiper replacement LH side
Side window wiper replacement RH side
Spout front side liner replacement LH side old type

Spout front side liner replacement RH side old type
Stone door replacement 492
Stub axle replacement LH carraro fwd from 01001101
Stub axle replacement LH carraro fwd till 01001100
Tentioner spring replacement LH side
Tentioner spring replacement RH side
Turbocharger replacement OM457LA
Upper feedroll shock absorber replacement 492
Upper feedrolls gearbox overhaul
Valve seal replacement 6 cilinder engine
Welding
Welding
Welding 3 hours
Welding 4 hours

7) A&M PREMIUM Warranty

All our equipment is inspected with the Harvester-Guard (R) inspection software. This certificate declares that this forage harvester has A&M PREMIUM warranty on:

1. All inspected CROP-FLOW components with a 3, 4 or 5 star rating.
2. All CROP-FLOW bearings which have status approved.

Warranty on repairs:

Components with 1 or 2 star rating are subject for repair and have no warranty. In case A&M Machinery is ordered to repair the 1 and 2 stars components then warranty is in place, as repair implies upgrade to 5 stars or status approved.

Eventually repairs are reported in the 'A&M PREMIUM or A&M EXCLUSIVE warranty certificate & terms' document.