

AM Machinery inspection certificate

New Holland 440FI

#23170



Price on request



AMMACHINERY

AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 440FI** built in **2009**, with our internal stock number **23170**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information: <https://www.ammachinery.nl/new-holland-440fi.html>

Technical specifications

Partnumber	23170	Year of manufacture	2009
------------	-------	---------------------	------

Options

2) Short Description

2009 New Holland 440FI 8 row rotary corn header. This header has been inspected and is good working.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23170	Brand	New holland
Model	440FI	Amount of rows	8
Working width	6 m	Autosteer sensor	N.A.
Header lateral tilt	N.A.	Header height control sensors	X*
Cutting knives	★ ★ ☆ ☆ ☆ ☆	Drum bearings	V
Cleaners	V	Drums	V
Drum cleaners / scrapers	V	Drive shaft	V
Drive line couplers	X*	Drive chains and belts	X*
Crop dividers	X*	Oil levels	X*
Down corn augers	V	Ground skid plates	X*
Fold cilinders	V	Hydraulic hoses/lines	X*
Transport accident prevention	N.A.	Support wheel(s)	N.A.
Support legs	X*	Wearplates	V

5) Recommended Repairs

Belt replacement crop divider kemper 300 RH side
 Cable repair
 Kemper 300 automatic header control sensor replacement LH
 Kemper 300 coupler LH side replacement
 Kemper 300 skid plate 3e left replacement
 Kemper 300 skid plate 5e left replacement
 Kemper 300 skid plate 6e left replacement
 Lock repair legs LH New style weld on
 Lock repair legs RH New style weld on
 New Holland 440FI hoses to coupler FR replacement
 New Holland 440FI Main drive gearbox outgoing shaft seal replacement
 Turn around knives 360
 Welding 2 hour
 Welding 2 hours