



Harvester Guard inspection certificate

Kemper 375 Plus fits CL

#24022-30



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 375 Plus fits CL** built in ,with our internal stock number **24022-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:
<https://www.ammachinery.nl/kemper-375-plus-fits-cl-24022-30.html>

Technical specifications

Partnumber	24022-30	Brand	Kemper
Model	375 Plus	Series	Claas

Options

2) Short Description

2015 Kemper 375 corn header that fits Claas. First use in 2016 including: multispeed gearbox with quick coupler, autosteer and autocontour. This header has been thoroughly inspected. The inspection report is available. This way you always know exactly what the state of your latest investment will be.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	24022	Brand	Kemper
Model	375 plus	Amount of rows	10
Working width (cm)	7.50 meter	Autosteer sensor	V
Header lateral tilt	V	Header height control sensors	V
Cutting knives	★ ★ ★ ☆ ☆	Drum bearings	V
Cleaners	V	Drums	V
Drum cleaners / scrapers	V	knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	N.A.	Crop dividers	V
Oil levels	V	Down corn augers	N.A.
Ground skid plates	V	Fold cilinders	X*
Hydraulic hoses/lines	V	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Wearplates	X*		

5)Recommended Repairs

Kemper 375+ seal repl 2e fold cilinder LH side

Claas 375+ From SN122139 to SN126768 feedroll wearplates