



Harvester Guard inspection certificate

New Holland 420FI

#23126-30



AMMACHINERY

Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 - 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 420FI** built in ,with our internal stock number **23126-30**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 300 points inspection report. Use this link to get below information:

<https://www.ammachinery.nl/new-holland-420fi-23126-30.html>

Technical specifications

Partnumber	23126-30	Brand	New Holland
Model	420FI		

Options

2) Short Description

For Sale, 2013, New Holland 420FI 6 row corn header. This header has been inspected. The inspection report can be downloaded from our website.

3) Product Images





4) Inspection Report

Condition
Header

Stocknumber	23126	Brand	New Holland
Model	420FI	Amount of rows	6
Working width (cm)	4.5 M	Autosteer sensor	N.A.
Header lateral tilt	N.A.	Header height control sensors	N.A.
Cutting knives	★★★★☆☆	Drum bearings	V
Cleaners	V	Drums	V
Drum cleaners / scrapers	X*	knife discs	V
Drive shaft	V	Drive line couplers	V
Drive chains and belts	V	Crop dividers	X*
Oil levels	V	Down corn augers	V
Ground skid plates	V	Fold cilinders	V
Hydraulic hoses/lines	X*	Transport accident prevention	N.A.
Support wheel(s)	N.A.	Support legs	V
Feeder auger	N.A.	Feeder auger bearings	N.A.
Wearplates	V		

5)Recommended Repairs

Welding 2 hours
Welding 3 hours
750 sfi hoses to coupler FR replacement