



Harvester Guard inspection certificate

Kemper 360 Plus fits CL

#25078-30



Industriestraat 23
5961 PH Horst
The Netherlands
T + 31 (0)77 – 2066603
sales@ammachinery.nl
<https://www.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **Kemper 360 Plus fits CL** built in ,with our internal stock number **25078-30**. We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run through our 300 points inspection report. Use this link to get below information:
<https://www.ammachinery.nl/kemper-360-plus-25078-30.html>

Technical specifications

Partnumber	25078-30	Brand	Kemper
Model	360 Plus		

Options

3) Product Images

4) Inspection Report

Condition Header

Stocknumber	25078	Brand	Kemper
Model	360 Plus	Amount of rows	8
Working width (cm)	6	Autosteer sensor	N.A.
Header lateral tilt	V	Header height control sensors	N.A.
Cutting knives	★☆☆☆☆	Drum bearings	V
Cleaners	X*	Drums	X*
Drum cleaners / scrapers	X*	knife discs	V
Drive shaft	V	Drive line couplers	X*
Drive chains and belts	N.A.	Crop dividers	X*
Oil levels	V	Down corn augers	N.A.
Ground skid plates	X*	Fold cilinders	V
Hydraulic hoses/lines	V	Transport accident prevention	V
Support wheel(s)	N.A.	Support legs	V
Wearplates	V		

5)Recommended Repairs

Kemper 300 coupler LH side replacement
 Kemper 300 coupler RH side replacement
 Kemper 300 main frame LH transport drum gearbox bearing repl
 Kemper 300 plus skid plate 1e left replacement
 Kemper 300 plus skid plate 2e left replacement
 Kemper 300 plus skid plate 3e left replacement
 Kemper 300 plus skid plate 4e left replacement
 Kemper 300 plus skid plate 5e left replacement
 Kemper 300 plus skid plate 6e left replacement
 Kemper 300 plus skid plate 7e left replacement
 Kemper 300 plus skid plate 8e left replacement
 Kemper 360 knife and cleaner replacement
 Kemper 360+ drum scrapers repl
 Kemper 360+ separator tips repl
 Maintenance
 Welding 2 hour