

Stocknummer: 20208
Brand: John Deere
Model: 7200
Built: 2006
Drive: 2 wheel drive
Serial number: Z07200X508100
Engine Hours shown: 2463
Cutting Hours shown: 1793



**Main Functionality test**

Hydrostatic drive (pressure and neutral)	approved
Transmission shifting	approved
4WD working (if applicable)	not applicable
Brakes and parking brake working	approved
Main clutch working	approved
LOC automatic/manual speed adjustment	approved
Header speed adjustment working	approved
Header height control working	approved
Spout turning	approved
Metal detector working	approved

Deflector	approved
Sharpening system	approved
Shearbar adjustment	approved
KP clearance adjustment	not applicable
Airconditioning cold	needs repair
Electrical functions cabin	approved
Radio	approved
Road & Working Lights	approved
Free of error codes	approved
Coolant fluid freezepoint	- 30 °C

**Front Tyres**

Brand:	Michelin
Size:	800/65R32
Profile in %:	90%

**Rear Tyres**

Brand:	Michelin
Size:	580/70R26
Profile in %:	80%

**Transition and spout**

Transition (housing and wear plates)	approved
Spout	approved
Liners	approved
Deflector	approved

**Main drive**

Main clutch	approved
Condition of main drive belt	approved

**Kernalprocessor**

Condition of the rollers	80%
Condition of the bearings	approved
Drive Belts	approved

**Feeding**

Condition of feedroller top front	80%	approved
Condition of feedroller top rear	80%	approved
Condition of metal detector roller	80%	approved
Condition of smooth roller	80%	approved
Feedroller bearings	approved	
Smooth roll scraper	needs repair	

**Cutterhead**

Knives quantity	50/28 installed	
Condition of knives	40%	approved
Shearbar	turned to the new side	
Current configuration	gras	
Cutterhead bearings	approved	
Sharpening stone	not applicable	

**Blower**

Condition of the bearings	approved	
Condition of blower paddles	10%	needs repair
Blower housing wear plates	approved	

**Attached header**

**Stocknumber header**

John Deere 630c	20164
-----------------	-------

**Available options**

- 1 Autolube
- 2 Silaspray innoculant system
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11

**Recommended repairs**

- 1 Smooth roll scraper replacement
- 2 A/C needs diagnose
- 3 Blower paddles replacement
- 4 Crack in windshield
- 5
- 6
- 7
- 8
- 9
- 10
- 11

**Our percentages are based on our opinion and do not constitute as part of the sales contract**

