

Stocknummer: 21073
Brand: Claas
Model: Jaguar 940
Built: 2017
Drive: 4 wheel drive
Serial number: 49701902
Engine Hours shown: 1731
Cutting Hours shown:



Main Functionality test

Hydrostatic drive (pressure and neutral)	approved
Transmission shifting	approved
4WD working (if applicable)	approved
Brakes and parking brake working	approved
Main clutch working	approved
LOC automatic/manual speed adjustment	approved
Header speed adjustment working	approved
Header height control working	approved
Spout turning	approved
Metal detector working	approved

Deflector	approved
Sharpening system	approved
Shearbar adjustment	approved
KP clearance adjustment	approved
Airconditioning cold	approved
Electrical functions cabin	approved
Radio	approved
Road & Working Lights	needs repair
Free of error codes	approved
Coolant fluid freezepoint	- 35 °C

Front Tyres

Brand:	Mitas
Size:	800/70r32
Profile in %:	90%

Rear Tyres

Brand:	Mitas
Size:	600/65r28
Profile in %:	90%

Transition and spout

Transition (housing and wear plates)	needs repair
Spout	approved
Liners	approved
Deflector	approved

Main drive

Main clutch	approved
Condition of main drive belt	approved

Kernalprocessor

Condition of the rollers	95%
Condition of the bearings	approved
Drive Belts	approved

Feeding

Condition of feedroller top front	75%	approved
Condition of feedroller top rear	75%	needs repair
Condition of metal detector roller	75%	approved
Condition of smooth roller	75%	approved
Feedroller bearings	needs repair	
Smooth roll scraper	approved	

Cutterhead

Knives quantity	V14/14 installed	
Condition of knives	85%	approved
Shearbar	needs repair	
Current configuration	gras	
Cutterhead bearings	approved	
Sharpening stone	like new	

Blower

Condition of the bearings	approved	
Condition of blower paddles	90%	approved
Blower housing wear plates	approved	

Attached header

Kemper 445	Stocknumber header
	#20286

Available options

- 1 Shredlage
- 2 Autolube
- 3 Innoculant system factory installed
- 4 Tire pressure system
- 5 Stone detector
- 6 Rear view camera
- 7 Spout camera
- 8
- 9
- 10
- 11

Recommended repairs

- 1 Needs new transition liners
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11

**Our technical value determination in % on parts and components is based on our opinion.
This does not constitute as part of the sales contract.**

